

CD<sub>3</sub>

Bar display

## **Features**

- Bar-graph display and beep indications
- High/low sensitive setting with range 12 ~ 1000V, 50/60Hz
- Flashlight





## **Technical Specifications**

Model	Metrix+ CD 3
Indicators	Bar-graph display and beep
Measuring range	High sensitivity: 12 ~ 1000V, 50/60Hz Low sensitivity: 48 ~ 1000V, 50/60Hz
Operating temperature	0 ~ 40°C
Storage temperature	-10 ~ 50°C
Humidity	<=95%
Altitude	2000m
Safety compliance	CAT III 1000V, CAT IV 600V
Power	2 x 1.5V AAA batteries
Standard Accessories	Main unit, batteries

Model and Specifications subject to change without notice.

Page 1 of 1 Rev 2010.01